


10

p20 x 1




Ø 4,2x13mm


n26/1 x 1



154x16x1mm



I




II

n26/1


p60

III




IV

5



682mm









11

f1 x 8
Ø 8x30mm





r1 x 16
Ø 15x12mm

z1 x 1
4mm

e27 x 16
Ø 6,3x50mm



x4




12

r23 x 16



45mm

c247 x 4






L=128/148mm




p25 x 8




Ø 4,2x25mm



x4



p25



x4

14

c241

13

g1x 24




Ø 2x20mm

p50 x 16






Ø 3x16mm




n1/2 x 4






L=300mm





x4







A=B





x4









14



15



16



17

