





# PRZEDPOKÓJ 1

→ 155 ↑ 190 ↘ 26




|                             |                           |                            |                              |                             |
|-----------------------------|---------------------------|----------------------------|------------------------------|-----------------------------|
| x 10<br><br>(a)             | x 29<br><br>(b)           | x 1 kpl.<br><br>(c)        | x 6<br><br>(d)               | x 6<br><br>(e)              |
| x 2<br><br>(f)              | x 8<br><br>(g)            | x 5<br><br>(h)             | x 1 kpl. (214 mm)<br><br>(i) |                             |
| x 2<br><br>(j)              | x 1<br><br>(k)            | x 2<br><br>(l)             | x 12<br><br>(m)              | x 2<br><br>(n)              |
| x 30<br>(3,5x16)<br><br>(p) | x 2<br>(M4-12)<br><br>(r) | x 8<br>(6,2x16)<br><br>(s) | x 50<br><br>(t)              | x 1<br><br>(w)              |
|                             |                           |                            |                              | x 28<br>(3,5x30)<br><br>(o) |
|                             |                           |                            |                              | x 1<br><br>(z)              |




1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW


a - OZNACZENIE AKCESORIÓW




8




9




10




11




12




13




14




15




16



17



18



19

